

Example of test area in a small office

Test area size = 4.5m^2

Number of measurements = 9 (0.5m apart)

Height of measurements = 0.8m (desk height)

Lux measurements must be taken at “working plane” level. So in office, this is desk height. For other areas like warehouse or car parks this is generally floor level.

